



INSPECTION REPORT

 TASQ QUALITY MANAGEMENT SERVICES LLP Rgd office: I-337, 2nd floor, Delta II, Greater Noida, G.B.Nagar. UP-201306, India Communication Address: K-1603, ANTARIKSH GOLF VIEW -1 Sector -78 Noida UP-201301 Mob: +919650999779 E.mail: tasqms@gmail.com www.tasqservices.com		Client: RACON BIDDING AND SOURCING PVT LTD Purchase order no : 83 R 2060 DT 13.10.2021 Project: RBS Equipment Name: Pulley Drive ,Snub , Tail Drg.& Rev.No.: 10779-2000-04-36, 10629-2000-18-00/1, 0629-2000-06-01/1, QAP No.: RBS APPROVED PO AND DRNGS
---	--	---

Report No: 31		Manufacturer Name and address: M/S HIC International Co Inc. D-136, Shankar Road New Delhi				
Inspection date: 5.03.2022						
Sr No	Item descriptions	QP. CL. no	Qty. offered	Qty. Accepted	Unit	Details of Inspection
01	HIC Pulley Drive Assembly with 90 mm Dia shaft and 12 mm rubber lagging. Bearing assembly	PO	01	2	Assy	1. Calibration of test instruments were ensured. 2. Pulley checked for its dimensions and found in line with the drawing. 3. TC verified
02	HIC Pulley Tail Assembly with 75 mm Dia shaft and 10 mm rubber lagging. Bearing assembly	specs	01	01	Assy	
03	HIC Pulley Snub assembly with 60 mm Dia shaft and 10 mm rubber lagging. Bearing assembly		02	02	Assy	

Discrepancy / Remark reported:		PULLEY accepted and released for further processing.	
Conclusion:		Pulleys identified with sl no- undersigned signature with marker	
Signature	Signature		
Name: Company Seal	Name : B D PRASAD		
For HIC International Co. Inc. 		 TASQ QMS Inspection Authority	

Authorised Signatory